

**NYARUTARAMA**



**PROGRESS REPORT**  
**JULY AND AUGUST 2023**

# PROGRESS REPORT

## Phase 1.



### INTRODUCTION

Harrington Golf Residence Phase 1 features 21 premium, exclusive 2 and 3 bed, all en suite apartments with separate guest cloak and laundry rooms. The units boast of impeccable finishing and large windows offering expansive panoramic views of the golf course across the living, dining, kitchen areas, letting in plenty of natural light.

Well-manicured outdoor garden and sitting spaces, recreational facilities such as swimming pool, children playground and a landscaped backyard offer the perfect recreation all within a secured, gated, highly-private community with 24-hour CCTV surveillance and ample parking spaces

### LOCATION

The site is located on plot No. 762 Nyarutarama, KIBIRARO II Cell, NYARUTARAMA Sector, REMERA district, Kigali, Rwanda.

| KG 552 St. | 1-minute walk from the Golf Course | 5-minute drive from MTN Center

## OVERALL SITE PROGRESS (PHASE I)

### EXCAVATION AND REMOVAL

ITEM	ACTIVITY	PROGRESS ONSITE
1	REMOVAL OF TREES	COMPLETE
2	EXCAVATION OF TOPSOIL AT AN AVERAGE OF 200MM TO REMOVE DEBRIS AND GRASS	COMPLETE
3	EXCAVATION TO REDUCE LEVEL UP TO BASEMENT 03 (PHASE I AND PHASE II)	COMPLETE
4	REMOVAL OF EXCAVATED SOIL TO THE DUMPING SITE APPROVED BY THE AUTHORITIES	COMPLETE
5	EXCAVATION OF BACK TRENCH RETAINING WALL	COMPLETE
6	CONSTRUCTION OF BACK TRENCH RETAINING WALL	COMPLETE
7	CONSTRUCTION OF BACK DRAINAGE CHANNEL	85%
8	CONSTRUCTION OF BACK RETAINING WALL	45%

### GROUND FLOOR (LEVEL 1)

ITEM	ACTIVITY	PROGRESS ONSITE
1	SETTING OUT OF THE STRIP FOUNDATION AND COLUMN	COMPLETE
2	EXACATION FOR STRIP FOUNDATION	COMPLETE
3	ANTI-TERMITE TREATMENT WAS SPRAYED ALL OVER THE AREA OF BASEMENT 03	COMPLETE
4	BLINDING CONCRETE	COMPLETE
5	FORMWORK FOR STRIP FOUNDATION	COMPLETE
6	STEELWORK FOR BOTH STRIP FOUNDATION AND SUB-COLUMN	COMPLETE
7	CASTING OF STRIP FOUNDATION AND SUB-COLUMN	COMPLETE

8	STEELWORK AND FORMWORK FOR COLUMNS AND RETAINING WALL ALONG GRID 23	COMPLETE
9	CASTING OF COLUMNS AND RETAINING WALL ALONG GRID 23	COMPLETE
10	CASTING OF LIFT PIT	COMPLETE
11	STAIRCASE FORMWORK AND STEELWORK	COMPLETE
12	CASTING OF STAIRCASE	COMPLETE
13	FORMWORK, STEELWORK & CASTING OF LIFT SHAFT	COMPLETE
14	CONSTRUCTION OF WALLS	60%

#### TERRACE FLOOR (LEVEL 2)

ITEM	ACTIVITY	PROGRESS ONSITE
1	FORMWORK FOR SLAB AND BEAM	COMPLETE
2	STEELWORK FOR SLAB AND BEAM	COMPLETE
3	LAYING OF MAXSPAN	COMPLETE
4	PLUMBING FIRST FIX	COMPLETE
5	ELECTRICAL FIRST FIX	COMPLETE
6	CASTING OF SLAB	COMPLETE
7	CURING OF SLAB	COMPLETE
8	STAIRCASE FORMWORK AND STEELWORK	COMPLETE
9	CASTING OF STAIRCASE	COMPLETE
10	FORMWORK, STEELWORK & CASTING OF LIFT SHAFT	COMPLETE
11	CONSTRUCTION OF WALLS	90%
12	EXTERIOR PLASTER	50%
13	FIXING OF PLUMBING PPR AND EVACUATION PIPES	60%
14	FIXING OF ELECTRICAL CONDUITS	15%

### FIRST FLOOR (LEVEL 3)

ITEM	ACTIVITY	PROGRESS ONSITE
1	FORMWORK FOR SLAB AND BEAM	COMPLETE
2	STEELWORK FOR SLAB AND BEAM	COMPLETE
3	LAYING OF MAXSPAN	COMPLETE
4	PLUMBING FIRST FIX	COMPLETE
5	ELECTRICAL FIRST FIX	COMPLETE
6	CASTING OF SLAB	COMPLETE
7	CURING OF SLAB	COMPLETE
8	STAIRCASE FORMWORK AND STEELWORK	COMPLETE
9	CASTING OF STAIRCASE	COMPLETE
10	FORMWORK, STEELWORK & CASTING OF LIFT SHAFT	COMPLETE
11	CONSTRUCTION OF WALLS	90%
12	EXTERIOR PLASTER	50%
13	FIXING OF PLUMBING PPR AND EVACUATION PIPES	60%

### SECOND FLOOR (LEVEL 4)

ITEM	ACTIVITY	PROGRESS ONSITE
1	FORMWORK FOR SLAB AND BEAM	COMPLETE
2	STEELWORK FOR SLAB AND BEAM	COMPLETE
3	LAYING OF MAXSPAN	COMPLETE
4	PLUMBING FIRST FIX	COMPLETE
5	ELECTRICAL FIRST FIX	COMPLETE
6	CASTING OF SLAB	COMPLETE

7	CURING OF SLAB	COMPLETE
8	STAIRCASE FORMWORK AND STEELWORK	COMPLETE
9	CASTING OF STAIRCASE	COMPLETE
10	FORMWORK, STEELWORK & CASTING OF LIFT SHAFT	COMPLETE
11	CONSTRUCTION OF WALLS	90%
12	EXTERIOR PLASTER	50%
13	FIXING OF PLUMBING PPR AND EVACUATION PIPES	60%

#### THIRD FLOOR (LEVEL 5)

ITEM	ACTIVITY	PROGRESS ONSITE
1	FORMWORK FOR SLAB AND BEAM	COMPLETE
2	STEELWORK FOR SLAB AND BEAM	COMPLETE
3	LAYING OF MAXSPAN	COMPLETE
4	PLUMBING FIRST FIX	COMPLETE
5	ELECTRICAL FIRST FIX	COMPLETE
6	CASTING OF SLAB	COMPLETE
7	CURING OF SLAB	COMPLETE
8	STAIRCASE FORMWORK AND STEELWORK	COMPLETE
9	CASTING OF STAIRCASE	COMPLETE
10	FORMWORK, STEELWORK & CASTING OF LIFT SHAFT	COMPLETE
11	CONSTRUCTION OF WALLS	90%
12	EXTERIOR PLASTER	50%
13	FIXING OF PLUMBING PPR AND EVACUATION PIPES	60%

**FOURTH FLOOR (LEVEL 6)**

ITEM	ACTIVITY	PROGRESS ONSITE
1	FORMWORK FOR SLAB AND BEAM	COMPLETE
2	STEELWORK FOR SLAB AND BEAM	COMPLETE
3	LAYING OF MAXSPAN	COMPLETE
4	PLUMBING FIRST FIX	COMPLETE
5	ELECTRICAL FIRST FIX	COMPLETE
6	CASTING OF SLAB	COMPLETE
7	CURING OF SLAB	COMPLETE
8	STAIRCASE FORMWORK AND STEELWORK	COMPLETE
9	CASTING OF STAIRCASE	COMPLETE
10	FORMWORK, STEELWORK & CASTING OF LIFT SHAFT	COMPLETE
11	CONSTRUCTION OF WALLS	90%
12	EXTERIOR PLASTER	50%
13	FIXING OF PLUMBING PPR AND EVACUATION PIPES	60%

**FIFTH FLOOR (LEVEL 7)**

ITEM	ACTIVITY	PROGRESS ONSITE
1	FORMWORK FOR SLAB AND BEAM	COMPLETE
2	STEELWORK FOR SLAB AND BEAM	COMPLETE
3	LAYING OF MAXSPAN	COMPLETE
4	PLUMBING FIRST FIX	COMPLETE
5	ELECTRICAL FIRST FIX	COMPLETE
6	CASTING OF SLAB	COMPLETE



7	CURING OF SLAB	COMPLETE
8	STAIRCASE FORMWORK AND STEELWORK	COMPLETE
9	CASTING OF STAIRCASE	COMPLETE
10	FORMWORK, STEELWORK & CASTING OF LIFT SHAFT	COMPLETE
11	CONSTRUCTION OF WALLS	90%
12	EXTERIOR PLASTER	50%
13	FIXING OF PLUMBING PPR AND EVACUATION PIPES	60%

#### ROOF (LEVEL 8)

ITEM	ACTIVITY	PROGRESS ONSITE
1	FORMWORK FOR SLAB AND BEAM	COMPLETE
2	STEELWORK FOR SLAB AND BEAM	COMPLETE
3	PLUMBING FIRST FIX	COMPLETE
4	ELECTRICAL FIRST FIX	COMPLETE
5	CASTING OF SLAB	COMPLETE
6	CURING OF SLAB	COMPLETE
7	FORMWORK, STEELWORK & CASTING OF LIFT SHAFT SERVICE LEVEL	15%



## PICTURES.



View from the ground floor



Walls separating the two units, plastering ongoing





Front view



Staircase



View of one of the apartments on the third floor, from the balcony





Open plan living, dining and kitchen area, showing the plumbing and electric ducts



The roof slab, cast





Views from the roof slab




Electrical ducts in one of the apartments living area





Views from inside one of the apartments on the first floor



Plumbing works in the kitchen area





One of the bedrooms



One of the bathrooms, with plumbing works ongoing





Bathroom



Electrical wiring in one of the bedrooms





Electrical wiring in one of the living areas

## **CONCLUSION**

The developer is committed to a timely completion to the project.